

FIG.1




FIG.2




FIG.3




FIG.4




FIG.5




FIG.6




FIG.7




FIG.8




FIG.9A




FIG.9B




FIG.10




FIG.11




FIG.12




FIG.13




FIG.14




FIG.15




FIG.16




FIG.17






FIG.18A




FREQUENCY IS
BEING SET

FIG.18B



FREQUENCY CANNOT
BE SET BECAUSE OF
SAME FREQUENCY


FIG.18C



TRANSMISSION FREQUENCY
OF ADDED ENDOSCOPE
IS BEING SET


A

FIG.18D



A


FIG.18E



A

B

FIG.18F



A

B

FIG.19




FIG. 20




FIG.21




FIG.22




FIG.24




FIG.23




FIG.25




FIG.26




FIG.27




FIG.28




FIG.29




FIG. 30




FIG.31

